

## **FIELD INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, July 15, 2020	Project Contact:	Brian Clauto
Spread H: Montgomery	MP228.5-227.5 AR 270, 268.01 ATWS 473, 474	Weather:	Dry
ACTIVE STAG	E OF CONSTRUCTION: (Check all that	apply)	
☐ Tree Felling	☐ Clearing/Grubbing ☐ Gra	ding $\Box$ Trench	hing 🔲 Stringing/Weldir
☐ Lowering/Backfilling	☐ Final Grading ☐ Ten	np. Stabilization   Perm.	Stabilization   Dormant
			Yes No N/A
	rols installed and implemented in accordate control plan and stormwater manageme		and 🖂 🗆
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
3. Areas of	offsite sediment deposition observed?		
Routine Main - N/A Ineffective Co	Inspected the following resources: S-Pere in place and appeared to be functional tenance: (72-Hour Deadline) from Notifical controls: (24-Hour Deadline) from Notifical ded Corrective Action: N/A	ioning, ation)	·G36

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: \_\_\_\_\_

Date: Wednesday, July 15, 2020



## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

Date: Wednesday, July 15, 2020

<u>Figure 1</u>: At MP 228.1 off of AR 270, the area is stabilized and ECD's are in place.



 <u>Figure 2</u>: Near MP 228, area is stabilized and ECD's are in place.



Figure 3. Designated stream S-G38, ECD's are in place.



Figure 4: Designated stream S-G36 on AR 268.01

